

SONATA(NF) >2009 > G 2.4 DOHC > Engine > Engine Control > P2096 Post Catalyst Fuel Trim System too Lean (Bank 1)  
> Verification of Vehicle Repair

### Verification of Vehicle Repair

After a repair, it is essential to verify that the fault has been corrected.

1. Connect GDS and select "DTC Analysis" mode.
2. Click "DTC Status" and confirm that "DTC Readiness Flag" indicates "Complete". If not, drive the vehicle within conditions noted in the freeze frame data or enable conditions.
3. Read "DTC Status" parameter.
4. Is parameter displayed "History(Not Present) fault"?

<b>YES</b>	<input type="checkbox"/> System performing to specification at this time. Clear the DTC.
<b>NO</b>	<input type="checkbox"/> Go to the applicable troubleshooting procedure.