



HYUNDAI Technical Service Bulletin

Group	Chassis
Number	07-50-007
Date	SEPTEMBER, 2007
Model	AZERA (TG)

Subject
**FRONT SHOCK ABSORBER REPLACEMENT -
 "HOLLOW" KNOCKING NOISE**

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

DESCRIPTION:


Some Azera vehicles produced from December 5, 2005 to February 26, 2007 may exhibit a "hollow" knocking noise from the front suspension while driving the vehicle over rough road surfaces at low speeds. This noise may originate from the front suspension shock absorber. This bulletin provides a procedure to correct this condition.

VEHICLES AFFECTED:

Model: Azera (TG)

Applicable vehicle production date range: Produced from Dec. 5, 2005 to Feb. 26, 2007

PARTS INFORMATION:

PART NAME	PART NUMBER		FIGURE	REMARK
	PREVIOUS	NEW		
Front shock absorber	54611-3L041	54611-3L040		2 each

NOTE: It is not necessary to replace both front shock absorbers if the condition is other than the subject ("hollow" knocking) noise condition. For example a leaking shock absorber. In that case replace only the incident (leaking) shock absorber with the same part number, 54611-3L041.

SERVICE PROCEDURE:

Replace the front shock absorbers following the shock absorber replacement procedure outlined in the Suspension System Section of the applicable Shop Manual.

WARRANTY INFORMATION:

OP CODE	OPERATION	OP TIME	CAUSAL PART NUMBER	NATURE	CAUSE
54650F02	Front shock absorber replacement (both sides)	1.4 MH	54611-3L040	*N29	**C99